Appleshaw and Penton Mewsey Infiltration Plan

Appendix A – work complete






Summary of work completed

Work type	Km of Sewer
Length surveyed	9.03
Length with no work required	5.67
Length sealed	3.18
Length to be sealed	0.18
Manholes sealed	18
Manholes to be sealed	4

Year	Surveyed (km)	Sewers sealed (km)	Manholes sealed
Pre 2014	7.63	1.38	0
2014	0.8	0.5	11
2015	0.2	1.1	7
2016	0.4	0.1	0
2017	0	0	0
2018	0	0.1	0
2019	0	0	0
2020	0	0	0
2021	0	0	0
2022	0	0	0
2023	0	0	0
2024	0	0	0

Note – Appleshaw is not a village that suffers infiltration and sewerage issues annually. The priority for sewer sealing work is lower than other systems which do suffer more frequently. This is reflected in the reduction in planned work after 2018 following completion of the most significant sealing work.






Appleshaw & Penton Mewsey	Manhole	Sewer km
Completed	18	3.18
Planned	4	0.18
Electroscan		0

Note – sewers shown as surveyed by cctv or electroscan with no corresponding sealing work have been determined to not require rehabilitation.





Note – sewers shown as surveyed by cctv or electroscan with no corresponding sealing work have been determined to not require rehabilitation.

